

School Board Work Session Dec. 13, 2016



Dinwiddie County Public Schools

P.O. Ben 7: 140:5 Devator Plank Road; Dinetddie; Virginia 23841. 504-469-4198 & Part 804-4469-4197



Introductions and Purpose of Meeting



Dinwiddie County Public Schools

- 2 New to Lawn - 6 How to Low- 12 New to Eslay =

Dinwiddie High School Dinwiddie Middle School Dinwiddie Elementary School Midway Elementary School Southside Elementary School Sunnyside Elementary School Sutherland Elementary School



- Lost over 200 students over the past 10 years
- Projected to lose approximately 80 over the next 10 years
- All elementary schools projecting a loss of students except for Southside, with a projected increase of 13 students over the next 10 years

OVERVIEW OF STUDY PROCESS

What Generates the Need for Capital Improvements?

NE	EDS TO BE ADDRESSED	STRATEGIES FOR ASSESSMENT
1.	Poor Conditions Simply stated, over time things wear out or "ugly out."	Perform a comprehensive conditions assessment including cost & timeline
2.	Functionality Problems Sometimes things can be in fine physical condition, but they just do not work well.	Identify the inadequacies through observations and interviews. Develop design solutions, timeline for implementation, and associated cost.
3.	Programmatic Changes The catch phrase here is that, over time, "needs and expectations change."	Make time for brainstorming, visioning, criteria development, and programming (quantifying the needs). Creatively explore multiple solutions and their cost impact. Consider stakeholder input.




SUMMARY OF APPROACH TO CAPITAL IMPROVEMENTS

- 1. Schools not needing action
 - Sutherland Elementary School
 - Dinwiddie High School
- 2. Schools needing small additions, limited renovations, or limited site improvements
 - Dinwiddie Elementary School (internal minor plus some site improvements for parking)
 - Midway Elementary School (small additions recommended + sitework)
- 3. Schools needing substantial renovation, expansion, or replacement
 - Dinwiddie Middle School
 - Sunnyside Elementary School
 - Southside Elementary School

FACILITY CONDITION ASSESSMENTS

- ➤ GOAL: Document present condition of each building to assist in forecasting funding requirements to address deficiencies, upgrades and/or renovations.
- FOCUS: Assessment is focused on a physical inspection of the site conditions and existing building structure (exterior and interior) to include the areas or building systems noted within each Executive Summary.
- AREAS / SYSTEMS:
- Civil / Site Conditions
- Architectural (Exterior)
- Architectural (Interior)
- ADA Compliance
- Safety / Security (OSHA)
- Building Code
- Roof Systems

- Mechanical Systems
- Electrical Systems
- Plumbing Systems
- Structural Systems
- Food Service Equipment
- Fire Suppression



DINWIDDIE ELEMENTARY SCHOOL

OVERALL CONDITION: GOOD


SIGNIFICANT ISSUES:

- Bus & Parent Pick-Up/Drop-Off Lane (Route & Safety Issues)
- ➤ Building Façade Precast Element Deterioration
- > Exterior Façade (Brick & Mortar Displacement)
- > Steel Lintel Rust Deterioration
- > Exterior Gutter/Soffit/Downspout Deterioration
- Exterior Route Accessibility (ADA)
- Kitchen Exhaust Hood (Not Code Compliant)

					Dinwiddie ES	
	OVERALL CONDI					
ASSESSED AREA	Dinwiddie ES	Southside ES	Sunnyside ES	Mid E	Fair	Transportation Department
Civil Assessment	Fair	Fair	Fair	Go	Fair	Good
Architectural Assessment (Exterior)	Fair	Fair	Good	Gc		Good
Architectural Assessment (Interior)	Good	Good	Good	Go	Good	Fair
ADA Compliance	Fair	Poor	Poor	Fa	Fair	Poor
Safety/Security (OSHA) Concerns	Poor	Fair	Poor	Fi-		Fair
Building Code Compliance	Poor	Good	Fair	Fa	Poor	Poor
Roof Systems Assessment	Good	Fair	Fair	Go	Poor	Good
Food Service Equipment Assessment	Fair	Fair	Fair	Gc	1001	N/A
Mechanical Systems Assessment	Good	Poor	Poor	Fa	Good	Fair
Electrical Systems Assessment	Good	Poor	Good	Go	Fair	Fair
Plumbing Systems Assessment	Good	Good	Good	Go	raii	Good
Structural Assessment	Fair	Fair	Good	Go	Good	Good
Fire Suppression System Assessment	Good	N/A	Good	Go	Good	N/A
					Good	
OVERALL	GOOD	FAIR	FAIR	GO	Good	GOOD
				Ī	Fair	
					Good	000000



DINWIDDIE ELEMENTARY SCHOOL



DINWIDDIE ELEMENTARY SCHOOL



DINWIDDIE ELEMENTARY SCHOOL COSTS

Order of Magnitude Costs

Site/Building Area	Square Feet (SF)	Cost/SF	Costs
General Sitework		LS	\$690,000
Existing Building Renovations	-	\$130	_
New Building Addition	-	\$210	-
New Security Entry Vestibule	240 SF	\$130	\$31,200
Soft Costs Factor			0.85
TOTAL EST. PROJECT COSTS	240 SF		\$848,471

MIDWAY ELEMENTARY SCHOOL

OVERALL CONDITION: GOOD

SIGNIFICANT ISSUES:

- Bus & Parent Pick-Up/Drop-Off Lane (Route & Safety Issues)
- > Building Façade Precast Element Deterioration
- Exterior Route Accessibility (ADA)
- > Stairwell Vertical Clearance Issues
- Diesel Fired Boiler(s) Deterioration
- Kitchen Exhaust Hood (Not Code Compliant)
- Kitchen Walk-In Coolers/Freezers (Undersized)

	OVERALL CONDITION							
ASSESSED AREA	Dinwiddie ES	Southside ES	Sunnyside ES	Midway ES	Dinwiddie MS	Transportation Midway		
Civil Assessment	Fair	Fair	Fair	Good	F	ES		
Architectural Assessment (Exterior)	Fair	Fair	Good	Good	P			
Architectural Assessment (Interior)	Good	Good	Good	Good	G	Good		
ADA Compliance	Fair	Poor	Poor	Fair	F	Good		
Safety/Security (OSHA) Concerns	Poor	Fair	Poor	Fair	P			
Building Code Compliance	Poor	Good	Fair	Fair	F	Good		
Roof Systems Assessment	Good	Fair	Fair	Good	F	Fair		
Food Service Equipment Assessment	Fair	Fair	Fair	Good	F	ran		
Mechanical Systems Assessment	Good	Poor	Poor	Fair	F	Fair		
Electrical Systems Assessment	Good	Poor	Good	Good	G	Fair		
Plumbing Systems Assessment	Good	Good	Good	Good	F	Fair		
Structural Assessment	Fair	Fair	Good	Good	F	Good		
Fire Suppression System Assessment	Good	N/A	Good	Good	F			
						Good		
OVERALL	GOOD	FAIR	FAIR	GOOD	F/	Fair		
		78		-	<u> </u>			
and the						Good		
		The latest with the latest window to the latest win				Good		



GOOD

Good

Good

MIDWAY ELEMENTARY SCHOOL



MIDWAY ELEMENTARY SCHOOL



MIDWAY ELEMENTARY SCHOOL COSTS

Site/Building Area	Square Feet (SF)	Cost/SF	Costs
General Sitework		LS	\$546,460
Existing Building Renovations	6,150 SF	\$130	\$799,500
New Building Addition	7,650 SF	\$210	\$1,606,500
Soft Costs Factor	0.85		
TOTAL EST. PROJECT COSTS	13,800 SF		\$3,473,482

OVERALL CONDITION: FAIR

SIGNIFICANT ISSUES:

- Bus & Parent Pick-Up/Drop-Off Lane (Route & Safety Issues)
- Exterior Façade (Brick & Mortar Displacement)
- > Building Façade Precast Element Deterioration
- > Steel Lintel Rust Deterioration
- Exterior Window/Door Replacement
- Exterior Gutter/Soffit/Downspout Deterioration
- **Exterior Caulk Deterioration**
- Laboratory Classroom Finishes Deteriorated
- Exterior Route Accessibility (ADA)
- Interior Route Accessibility (ADA)
- > Roof System Replacement
- **➤** Kitchen Exhaust Hood Replacement
- ➤ Mechanical (HVAC) Equipment Replacement
- ➤ Mechanical (HVAC) Air Distribution Replacement

				Diffwidale MS		
ASSESSED AREA	Dinwiddie ES	Southside ES	Sunr	Fair	Dinwiddie MS	Transportation Department
Civil Assessment	Fair	Fair		Poor	Fair	Good
Architectural Assessment (Exterior)	Fair	Fair	6	1001	Poor	Good
Architectural Assessment (Interior)	Good	Good	e	Good	Good	Fair
ADA Compliance	Fair	Poor	1	Fair	Fair	Poor
Safety/Security (OSHA) Concerns	Poor	Fair	ı	Fair	Poor	Fair
Building Code Compliance	Poor	Good		Poor	Fair	Poor
Roof Systems Assessment	Good	Fair	t		Fair	Good
Food Service Equipment Assessment	Fair	Fair		Fair	Fair	N/A
Mechanical Systems Assessment	Good	Poor	F	Fair	Fair	Fair
Electrical Systems Assessment	Good	Poor	c		Good	Fair
Plumbing Systems Assessment	Good	Good	e	Fair	Fair	Good
Structural Assessment	Fair	Fair	e	Fair	Fair	Good
Fire Suppression System Assessment	Good	N/A	c	- Tun	Fair	N/A
				Good		
OVERALL	GOOD	FAIR	F	Fair	FAIR	GOOD
THE AND		. 44	_ ļ	Fair		
				Fair		
			T	Fair	1	

Dinwiddie MS

FAIR









DINWIDDIE MIDDLE SCHOOL COSTS

Site/Building Area	Square Feet (SF)	Cost/SF	Costs
General Sitework		LS	\$327,875
Existing Building Renovations	148,971 SF	\$130	\$19,366,230
New Building Addition	39,650 SF	\$210	\$8,326,500
Soft Costs Factor			0.85
TOTAL EST. PROJECT COSTS	188,621 SF		\$32,965,418

SUNNYSIDE ELEMENTARY SCHOOL

OVERALL CONDITION: FAIR

SIGNIFICANT ISSUES:

- Bus & Parent Pick-Up/Drop-Off Lane (Route & Safety Issues)
- > Exterior Façade (Brick & Mortar Displacement)
- Exterior Route Accessibility (ADA)
- Interior Route Accessibility (ADA)
- Roof Expansion Joint Deterioration
- Scupper/Roof Drains (Quantity)
- Kitchen Exhaust Hood (Not Code Compliant)
- > Mechanical (HVAC) Equipment Deterioration
- Mechanical (HVAC) Air Distribution (Interior Lined)

			OVERAL	L CONDITION		
ASSESSED AREA	Dinwiddie ES	Southside ES	Sunnyside ES	Midway ES	Fair	portatio
Civil Assessment	Fair	Fair	Fair	Good	Good	ood
Architectural Assessment (Exterior)	Fair	Fair	Good	Good		ood
Architectural Assessment (Interior)	Good	Good	Good	Good	Good	air
ADA Compliance	Fair	Poor	Poor	Fair	Dane	oor
Safety/Security (OSHA) Concerns	Poor	Fair	Poor	Fair	Poor	Fair
Building Code Compliance	Poor	Good	Fair	Fair	Poor	oor
Roof Systems Assessment	Good	Fair	Fair	Good		ood
ood Service Equipment Assessment	Fair	Fair	Fair	Good	Fair	N/A
Mechanical Systems Assessment	Good	Poor	Poor	Fair	Fair	Fair
Electrical Systems Assessment	Good	Poor	Good	Good		cair
Plumbing Systems Assessment	Good	Good	Good	Good	Fair	ood
Structural Assessment	Fair	Fair	Good	Good	Poor	ood
Fire Suppression System Assessment	Good	N/A	Good	Good		I/A
					Good	
OVERALL	GOOD	FAIR	FAIR	GOOD		DOD




FAIR

Good

Good

Sunnyside ES

SUNNYSIDE ELEMENTARY SCHOOL



SUNNYSIDE ELEMENTARY SCHOOL



RRMM ARCHITECTS

SUNNYSIDE ELEMENTARY SCHOOL COSTS

Site/Building Area	Square Feet (SF)	Cost/SF	Costs		
General Sitework		LS	\$546,460		
Existing Building Renovations	37,416 SF	\$130	\$4,864,080		
New Building Addition	26,212 SF	\$210	\$5,504,520		
Soft Costs Factor 0.85					
TOTAL EST. PROJECT COSTS	63,628 SF		\$12,841,247		

SOUTHSIDE ELEMENTARY SCHOOL

OVERALL CONDITION: FAIR

SIGNIFICANT ISSUES:

- Limited Site Size/Layout Options
- ➤ Site Drainage & Utilities (Well/Septic) Limitations
- Bus & Parent Pick-Up/Drop-Off Lane (Route & Safety Issues)
- Exterior Façade (Brick & Mortar Displacement)
- **Exterior Caulk Deterioration**
- Exterior Route Accessibility (ADA)
- Interior Route Accessibility (ADA)
- Roof System Issues
- Scupper/Roof Drains (Quantity)
- Kitchen Exhaust Hood Replacement
- ➤ Mechanical (HVAC) Equipment Replacement
- ➤ Mechanical (HVAC) Air Distribution Replacement
- Electrical System/Distribution Replacement
- > Interior Lighting Replacement
- > Fire Alarm System Upgrade

			- 1		
			OVERALL C		
ASSESSED AREA	Dinwiddie ES	Southside ES	Sunnyside ES	Fair	S Transportation Department
Civil Assessment	Fair	Fair	Fair	Fair	Good
Architectural Assessment (Exterior)	Fair	Fair	Good	Good	Good
Architectural Assessment (Interior)	Good	Good	Good	dood	Fair
ADA Compliance	Fair	Poor	Poor	Poor	Poor
Safety/Security (OSHA) Concerns	Poor	Fair	Poor	F-1-	Fair
Building Code Compliance	Poor	Good	Fair	Fair	Poor
Roof Systems Assessment	Good	Fair	Fair	Good	Good
Food Service Equipment Assessment	Fair	Fair	Fair		N/A
Mechanical Systems Assessment	Good	Poor	Poor	Fair	Fair
Electrical Systems Assessment	Good	Poor	Good	Fair	Fair
Plumbing Systems Assessment	Good	Good	Good		Good
Structural Assessment	Fair	Fair	Good	Poor	Good
Fire Suppression System Assessment	Good	N/A	Good	Poor	N/A
OVERALL	GOOD	FAIR	FAIR	Good	GOOD



FAIR

Fair

N/A

Southside ES

SOUTHSIDE ELEMENTARY SCHOOL



Southside Elementary School Cost Comparisons Between New and Renovation

Variables that can affect cost comparison

- 1. SF per Student
 - Programs number of Special Ed, 21st Century Design Initiatives, community use, etc.
 - Capacity Calculations DOE standard teacher/pupil ratios vs. division standards
 - Building Capacity smaller capacity schools have higher ratio of core spaces to academic spaces, thus higher SF/student
- 2. \$ per SF
 - Exceptional Costs site utilities, site acquisition, hazmats, construction phasing
 - Quality
 - Furniture, fixtures and equipment (FFE) investment
 - Inflation or escalation time

Renovation of 550-student Southside (w/ assumptions) – \$16,701,910 total cost in today's dollars

Assumptions:

- \$130/SF renovation cost average
- Public water and sewer extensions (2 miles)
- 18 months of classroom trailer rental
- Renovation includes all of existing building + gym + at least one classroom added

New Replacement of 550-student Southside (w/ assumptions) – \$19,853,500 total cost in today's dollars

Assumptions:


- 74,250 SF building based on 135 SF/student
- Site acquisition required (min. 15 acres @ \$58,500/acre)
- Sewer and water available
- \$30/SF for site and \$180/SF for building total of \$210/SF for construction costs

New Replacement of 550-student Southside (w/ assumptions) – \$21,516,700 total cost in today's dollars

Assumptions:

- 80,850 SF building based on 147 SF/student
- Site acquisition required
- Sewer and water available
- \$30/SF for site and \$180/SF for building total of \$210/SF for construction costs

Assessment: Renovation is between 78% and 84% of the cost of new construction.



QUESTIONS?

School Board Work Session Dec. 13, 2016

